

Instructions to update Firmware for IDS Peak cameras

I am pleased to release instructions for updating the firmware for products including IDS Peak cameras. Specifically relevant to the earlier Mantis PIXO and Lynx EVO SmartCam 50 cameras, updating the firmware will improve the performance and stability of the products. Firmware updates are now being applied to all Mantis PIXO and SmartCam 50 production units.


[IDS camera firmware update procedure.](#)

Procedure updates firmware to prevent the 'CriticalCoreError' message appearing on some units.


Step 1

To retrieve the latest camera firmware go to IDS-imaging website:


<https://en.ids-imaging.com/downloads.html>




In the support tab, select downloads.



Type in U3-3682XLE-C into the search bar and select the camera.



Scroll down on the web page slightly and click on firmware, this will reveal the latest cut of camera firmware, click on the vision firmware.



Open IDS peak software and click open camera manager.

